


LAPPING PATTERN DIAGRAM for small SONiC lapkit

Follow the freehand line pattern when lapping a head or block. For cast iron use the coarse SSC compound and for alloy use the coarse or fine compound.



Scale size of the Tool and
Engine surfaces

